

Vulcan Materials CO
Form 8-K
June 11, 2012

UNITED STATES

SECURITIES AND EXCHANGE COMMISSION
Washington, DC 20549

CURRENT REPORT

Pursuant to Section 13 or 15(d) of the Securities Exchange Act of 1934

Date of Report (Date of earliest event reported): June 6, 2012

VULCAN MATERIALS COMPANY

(Exact name of registrant as specified in its charter)

New Jersey 001-33841 20-8579133
(State or other jurisdiction of incorporation) (Commission File Number) (IRS Employer Identification No.)

1200 Urban Center Drive
Birmingham, Alabama 35242

(Address of principal executive offices) (zip code)

(205) 298-3000

Registrant's telephone number, including area code:

Not Applicable

Edgar Filing: Vulcan Materials CO - Form 8-K

(Former name or former address if changed since last report)

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligations of the registrant under any of the following provisions:

- .. Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
- .. Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
- .. Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
- .. Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

Item 1.04 Mine Safety

On June 6, 2012, Vulcan Materials Company (the “Company”) received an imminent danger order issued by the Mine Safety and Health Administration (“MSHA”) under section 107(a) of the Federal Mine Safety and Health Act of 1977 at our Royal Stone Quarry located in Richmond, Virginia. The employee, a plant greaser, was observed by the MSHA Inspector reaching over the bend pulley guard of the gravity take-up system and the top rail inside the box frame of C-2 conveyor at the Primary Plant to remove a grease hose with the conveyor running. According to the Order, the employee put himself at danger of being entangled in the conveyor between the top rollers and the conveyor belt. The employee was not injured.

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

Vulcan Materials Company

Date: June 11, 2012 By: /s/ Robert A. Wason IV
Robert A. Wason IV